JUMBO MINING CO.

6305 Fern Spring Cove Austin, Texas 78730 (512) 346-4537 Telex # 76-7177

Mr. Kiran L. Bhayani, P.E. Manager, Design Evaluation Bureau of Pollution Control Utah Department of Health Division of Environmental Health P.O. Box 16690 Salt Lake City, Utah 84116-0690

Dear Mr. Bhayani:

June 1, 1990 File: UDH610

C ... _

Re: DRUM MINE PROJECT Your letter April 27, 1990

In your referenced letter you requested that we submit for your review a map showing our monitoring well locations, lab testing results, as well as any new information regarding pollutants in the monitoring well system.

Please find attached information which is responsive to the above requests. It is worth noting that a trace of cyanide was reported in a sample of water from the Busby Spring, located a mile or two distant from the heaps, and several hundred feet above the tops of the highest heaps. I believe this points to the limits of accuracy of the analytical methods available, rather than to a true cyanide content. Alternatively, it could mean that a small amount of cyanide may exist from natural sources in this area.

Since reviewing this information with Mack Croft and David Rupp on site, we have attempted to determine flow rates by pumping from the some of the monitoring wells. It is evident from these pumping tests that the porosity and/or permeability of these rock formations is very limited, and, from this it can be inferred that the quantity of water contained in this area is minimal, certainly not enough to meet the definition of an "aquifer", as far as we can determine.

From the information we have gathered to date, we can only conclude that there is a small amount of water on a perched water table in the area indicated, and that the water quality in it meets drinking water standards, with respect to the trace of cyanide in it. (See attached log of Monitoring Holes and attached analyses certificates from the Southern Utah State Testing Lab.)

The fact that the level of the water table in many instances is above the bottom of the heaps which have been active since we took over the property two years ago, leads us to the conclusion that this trace of cyanide likely came from heap No. 6 or No. 3 LG, when they were being leached several years ago. Neither of these heaps have been leached at any time since we took over the property over two years ago. We base

this conclusion on the relative elevations of the heaps and the fact that there is evidence that both had leaked at one time. (See attached water levels in the monitoring holes and the water level contours drawn on the location map from these figures.)

We will continue to monitor this situation throughout the summer and advise you if we see any significant changes.

Pursuant to the 60 day leak test on heaps No. 7 and No. 2LG, please find enclosed copies of the Neutron Logging of the test wells located down dip from these two heaps. These tests were completed recently in anticipation of starting of the sprinkling test of these two heaps, pursuant to our earlier agreement thereon. As you will recall, this Neutron logging is a repeat of that done last November, following which the sprinkling was aborted due to freezing weather. You have in your files the earlier set of logs.

As you are aware, the OGM has prohibited us from going forth with this test until the reclamation issue on these heaps has been resolved with the prior owner/operator of the property. We believe that this is now the only issue to be resolved before this test starts. Please let us know if you do not agree.

Sincerely yours,

E. B. King President

cc: (without Neutron Logs)

Roger Foisey, Central Utah District Health Dept., Richfield. BLM, House Range Resource Area, Fillmore Wayne Hedberg, Oil, Gas & Mining D. Hartshorn, Drum Mine

Drum Mine Mo toring Holes									
Hole	Hole Depth	Collar Elev	Water	Depth. to Water	" PH	CN-	PPM		3
1 2 3	66' 100' 124'	5950 5940 5935	5920 5885 5873	30' 55' 62'	7.6 7.2 7.0	ND.			
7 8 9 10	139' 50' 50' 50'	5958 5958 5971 5974	5929 5922 	29', ' 36' - 33'	7.1 7.3 -	ND. 0.07	0.60	*	
17 18 19	49' 49' 71'	5960 5972 5987	5937 5951 5962	23' 21', 35'	7.4	0,12 ND	B-44	*	
34 25	105' 105' 105'	5998 6006 6006	5922 5975 5934	76' 31' 72	8.2 8.2 8.0	2 2 2			
H 20	105' 105'	5995 5990	5914 5887	81' 103'	8.1 7.9	D D			
31 32	100' 105'	5967 6015	5948 6956	19' 59'	7.7 8.7	ND DN			
33 34 35	105' 105', 105'	5957 5949 5940	5938 5940 5925	19'	8.0 7.7 7.8	D D D D D D D D D D D D D D D D D D D			
NH-81 (Busby		_		_	7.8	0.03	0.08	*	
	and the state of t	AP NEUTRALIZAT	enter in mentalisation in annual and and			0.70	0.75		
	NOTE -		FECTABLE BY CONT ES BY SOUTHERN			:			
		•	- 14 CIPIA	- मस्य 🗝 । १४ । 🚓	ICA IING	MR ~	ATTACK	CI)	KCHOICI
				•				i	
·		المر.			:	•		. :	;

SOUTHERN UTAH STATE TESTING LAB SCIENCE aldg. - ROOM 010 351 WEST CENTER CEDAR CITY, UT 84720

SAMPLE NUMBER : K0900234

COST : 23.50

TIME COLLECTED: 13:00 DATE COLLECTED: 3-8-90

DATE RECIVED : 12-MAR-1990

DATE COMPLETED : 22-MAR-1990

DATE SENT : 3-29-90

INVOICE NUMBER : G-K0900234

COLLECTOR : DAVE HARTSHORN

BUSBY SPRING SITE LOCATION : MH-B1

SEND RESULTS TO : JUMBO MINING P.C. BOX 999

DELTA, UT 84624

ALL RESULTS IN MILLIGRAMS/LITER (ppm)

CHECKS OXYGEN GEN PRAM CATIONS CATIONS ANIONS

0.08 CN

TOTAL

0.03 Fr-CN

FREE

SOUTHERN UTAH STATE TESTING LAB SCIENCE BLDG. - ROOM O'TO STATE TESTING LAB STATE TESTING LAB

.

SAMPLE NUMBER : K0900150 COST : \$30.10 ...

TIME COLLECTED: 13:30 DATE COLLECTED: 2-15-90

DATE RECIVED : 21-FEB-1990

DATE COMPLETED: 19-MAR-1990 DATE SENT: 3-20-90

INVOICE NUMBER : G-K0900150

COLLECTOR : L. SCHENA

SITE LOCATION : MH-17

`

SEND RESULTS TO : JUMBO MINING
P.O. BOX 999

DELTA, UT 84624

ALL RESULTS IN MILLIGRAMS/LITER (ppm)

'ANIONS CATIONS CATIONS GEN PRAM DXYGEN CHECKS

0.44 CN

TOTAL

NOTES :

)

5 . K

0.12 Fr-CN

SOUTHERN UTAH STATE TESTING + LAB +> SCIENCE BLDG. - ROOM 010

CEDAR CITY, UT 84720

SAMPLE NUMBER : K0900151 CGST : \$30.10

TIME COLLECTED: 13:00 DATE COLLECTED: 2-15-90

DATE RECIVED : 21-FEB-1990

DATE SENT : 3-20-90 DATE COMPLETED : 19-MAR-1990

INVOICE NUMBER : G-K0900151

COLLECTOR : L. SCHENA

SITE LOCATION : MH-8

``)

SEND RESULTS TO : JUMBO MINING P.O. BOX 999

DELTA, UT 84624

ALL RESULTS IN MILLIGRAMS/LITER (ppm)

ANIONS CATIONS CATIONS GEN PRAM DXYGEN CHECKS

0.60 CN

TOTAL

NOTES :

11. K

0.07 Fr-CN

